

*Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.*

# Wire Connectors and Soldering Lugs

**COMPANY****E137735****BM SPA**

VIA MILANO 54/56

ROZZANO, MI 20089 Italy

*View model for additional information*

**Copper Cable Lugs with and without Inspection Window and with and without Flared Entry**, Model(s): [BM011071](#), [BM011191](#), [BM011251](#), [BM011311](#), [BM012191](#), [BM012251](#), [BM012311](#), [BM013190](#), [BM013191](#), [BM013250](#), [BM013251](#), [BM013310](#), [BM013311](#), [BM013370](#), [BM013371](#), [BM013431](#)

**Crimp connectors**, Model(s): [BM80425](#), [BM80431](#), [BM80531](#), [BM80537](#), [BM80543](#), [BM80631](#), [BM80637](#), [BM80643](#), [BM80649](#), [BM80737](#), [BM80743](#), [BM80749](#), [BM80837](#), [BM80843](#), [BM80849](#), [BM80861](#), [BM80937](#), [BM80943](#), [BM80949](#), [BM80961](#), [BM83143](#), [BM83149](#), [BM83161](#), [BM83243](#), [BM83249](#), [BM83261](#), [BM83267](#), [BM83343](#), [BM83349](#), [BM83361](#), [BM83367](#), [BM83443](#), [BM83449](#), [BM83461](#), [BM83467](#), [BM83549](#), [BM83561](#), [BM83567](#)

**Crimp connectors w/o inspection hole**, Model(s): [BM014191](#), [BM014311](#), [BM014371](#), [BM014431](#), [BM014491](#), [BM015251](#), [BM015311](#), [BM015371](#), [BM015431](#), [BM015491](#), [BM016251](#), [BM016311](#), [BM016371](#), [BM016431](#), [BM016491](#), [BM017311](#), [BM017371](#), [BM017431](#), [BM017491](#), [BM018311](#), [BM018371](#), [BM018431](#), [BM018491](#), [BM018551](#), [BM019311](#), [BM019371](#), [BM019431](#), [BM019491](#), [BM019611](#), [BM031371](#), [BM031431](#), [BM031491](#), [BM031551](#), [BM031611](#), [BM032371](#), [BM032431](#), [BM032491](#), [BM032551](#), [BM032611](#), [BM033371](#), [BM033431](#), [BM033491](#), [BM033551](#), [BM033611](#), [BM033671](#), [BM034431](#), [BM034491](#), [BM034551](#), [BM034611](#), [BM034671](#), [BM035491](#), [BM035551](#), [BM035611](#), [BM035671](#), [BM036491](#), [BM036551](#), [BM036611](#), [BM036671](#), [BM036691](#)

**Crimp connectors, double hole tongue**, Model(s): [BM73210](#)

**Crimp connectors, fork**, Model(s): [BM01420](#), [BM01426](#), [BM01523](#), [BM01526](#)

**Crimp connectors, tongue 45 degrees**, Model(s): [BM0141945](#), [BM0143145](#), [BM0143745](#), [BM0144345](#), [BM0144945](#), [BM0152545](#), [BM0153145](#), [BM0153745](#), [BM0154345](#), [BM0154945](#), [BM0162545](#), [BM0163145](#), [BM0163745](#), [BM0164345](#), [BM0164945](#), [BM0173145](#), [BM0173745](#), [BM0174345](#), [BM0174945](#), [BM0183145](#), [BM0183745](#), [BM0184345](#), [BM0184945](#), [BM0185545](#), [BM0193145](#), [BM0193745](#), [BM0194345](#), [BM0194945](#), [BM0195545](#), [BM0196145](#), [BM0313745](#), [BM0314345](#), [BM0314945](#), [BM0315545](#), [BM0316145](#), [BM0323745](#), [BM0324345](#), [BM0324945](#), [BM0325545](#), [BM0326145](#), [BM0333745](#), [BM0334345](#), [BM0334945](#), [BM0335545](#), [BM0336145](#), [BM0336745](#), [BM0344345](#), [BM0344945](#), [BM0345545](#), [BM0346145](#), [BM0346745](#), [BM0354945](#), [BM0355545](#), [BM0356145](#), [BM0356745](#)

**Crimp connectors, tongue 90 degrees**, Model(s): [BM014199](#), [BM014319](#), [BM014379](#), [BM014439](#), [BM014499](#), [BM015259](#), [BM015319](#), [BM015379](#), [BM015439](#), [BM015499](#), [BM016259](#), [BM016319](#), [BM016379](#), [BM016439](#), [BM016499](#), [BM017319](#), [BM017379](#), [BM017439](#), [BM017499](#), [BM018319](#), [BM018379](#), [BM018439](#), [BM018499](#), [BM018559](#), [BM019319](#), [BM019379](#), [BM019439](#), [BM019499](#), [BM019559](#), [BM019619](#), [BM031379](#), [BM031439](#), [BM031499](#), [BM031559](#), [BM031619](#), [BM032379](#), [BM032439](#), [BM032499](#), [BM032559](#), [BM032619](#), [BM033379](#), [BM033439](#), [BM033499](#), [BM033559](#), [BM033619](#)

BM033679, BM034439, BM034499, BM034559, BM034619, BM034679, BM035499, BM035559, BM035619, BM035679, BM805379, BM805439, BM806499, BM807499, BM808499, BM809499, BM831499, BM831619, BM832619  
**Splicing wire connectors**, Model(s): 00110N, 00110N3, 00110N4, 00160, 00160, 00170, 00170H, 00210N, 00210N3, 00210N4, 00260, 00270, 00270H, 00270T, 00360, 00370, 00370H, 00370T, 00470, 00470H, 01160, 01260, 01360, 80160, 80260, 80260, 80260[#], 80360, BM00160, BM00162, BM00170, BM00260, BM00262, BM00270, BM00360, BM00362, BM00370, BM80160, BM80260, BM80360, MW15AV, MW15GI, MW15GR, MW15NE, MW25AR, MW25AV, MW25BL, MW25GI, MW25NE, MW25RO, MW25ROP, MW60GI, MW60GIP

**Terminal connectors**, Model(s): BM00101, BM00102, BM00107, BM00108, BM00109, BM00113, BM00114, BM00119, BM00120, BM00125, BM00126, BM00131, BM00132, BM00137, BM00143, BM00152, BM00153, BM00201, BM00202, BM00207, BM00208, BM00209, BM00219, BM00220, BM00225, BM00226, BM00231, BM00232, BM00237, BM00243, BM00252, BM00253, BM00313, BM00314, BM00319, BM00320, BM00325, BM00326, BM00331, BM00332, BM00337, BM00338, BM00343, BM00344, BM00352, BM00353, BM01419, BM01431, BM01437, BM01443, BM01449, BM01450, BM01460, BM01525, BM01531, BM01537, BM01543, BM01549, BM01550, BM01560, BM01625, BM01631, BM01637, BM01643, BM01649, BM01650, BM01660, BM01731, BM017313, BM017314, BM01737, BM017374, BM01743, BM017434, BM01749, BM017494, BM01750, BM01760, BM017604, BM01831, BM018313, BM018314, BM01837, BM018373, BM018374, BM01843, BM018433, BM018434, BM01849, BM018494, BM01850, BM01855, BM01860, BM018604, BM01931, BM019313, BM019314, BM01937, BM019374, BM01943, BM019433, BM019434, BM01949, BM019494, BM01950, BM01955, BM019554, BM01960, BM019604, BM01961, BM019614, BM02050, BM02425, BM02431, BM02437, BM02443, BM02449, BM02525, BM02531, BM02537, BM02543, BM02549, BM02625, BM02631, BM02637, BM02643, BM02649, BM02661, BM02731, BM02737, BM02743, BM02749, BM02761, BM02831, BM02837, BM02843, BM02849, BM02861, BM02931, BM02937, BM02943, BM02949, BM02961, BM03137, BM031373, BM031374, BM03143, BM031433, BM031434, BM03149, BM031494, BM03155, BM031554, BM03160, BM031604, BM03161, BM031614, BM03237, BM032373, BM032374, BM03243, BM032433, BM032434, BM03249, BM032494, BM03255, BM032554, BM03260, BM03261, BM032614, BM03337, BM033373, BM033374, BM03343, BM033433, BM033434, BM03349, BM033494, BM03355, BM033554, BM03360, BM03361, BM033614, BM03367, BM033674, BM03443, BM034435, BM03449, BM034493, BM034494, BM034495, BM03455, BM034554, BM034555, BM03460, BM034605, BM03461, BM034614, BM034615, BM03467, BM034674, BM034675, BM03543, BM035433, BM03549, BM035493, BM03555, BM03560, BM03561, BM03567, BM03649, BM03655, BM03660, BM03661, BM03667, BM03669, BM037494, BM037554, BM037604, BM037614, BM037674, BM04137, BM04143, BM04149, BM04161, BM04237, BM04243, BM04249, BM04261, BM04343, BM04349, BM04361, BM071537, BM071637, BM071643, BM071737, BM0717374, BM071743, BM0717434, BM071837, BM071843, BM0718434, BM071849, BM0718494, BM071943, BM0719434, BM071949, BM0719494, BM071955, BM0719554, BM071961, BM0719614, BM072300, BM073143, BM0731434, BM073149, BM0731494, BM073155, BM0731554, BM073161, BM0731614, BM073243, BM073249, BM073255, BM073261, BM073300, BM073349, BM073355, BM073361, BM073367, BM0734495, BM073455, BM0734555, BM073461, BM0734615, BM073467, BM0734675, BM073555, BM073561, BM073567, BM073661, BM073667, BM0737614, BM90107, BM90108, BM90113, BM90114, BM90119, BM90120, BM90125, BM90126, BM90131, BM90132, BM90137, BM90143, BM90150, BM90151, BM90207, BM90208, BM90213, BM90219, BM90220, BM90225, BM90226, BM90231, BM90232, BM90237, BM90243, BM90250, BM90251, BM90314, BM90319, BM90320, BM90325, BM90326, BM90331, BM90332, BM90337, BM90343, BM90350

Last Updated on 2026-02-10

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2026 UL LLC."

*Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.*

# Wire Connectors and Soldering Lugs Certified for Canada

**COMPANY****BM SPA**

VIA MILANO 54/56

ROZZANO, MI 20089 Italy

**E137735**

*View model for additional information*

**Copper Cable Lugs with and without Inspection Window and with and without Flared Entry, Model(s):** [BM011071](#), [BM011191](#), [BM011251](#), [BM011311](#), [BM012191](#), [BM012251](#), [BM012311](#), [BM013190](#), [BM013191](#), [BM013250](#), [BM013251](#), [BM013310](#), [BM013311](#), [BM013370](#), [BM013371](#), [BM013431](#)

**Crimp connectors, Model(s):** [BM80425](#), [BM80431](#), [BM80531](#), [BM80537](#), [BM80543](#), [BM80631](#), [BM80637](#), [BM80643](#), [BM80649](#), [BM80737](#), [BM80743](#), [BM80749](#), [BM80837](#), [BM80843](#), [BM80849](#), [BM80861](#), [BM80937](#), [BM80943](#), [BM80949](#), [BM80961](#), [BM83143](#), [BM83149](#), [BM83161](#), [BM83243](#), [BM83249](#), [BM83261](#), [BM83267](#), [BM83343](#), [BM83349](#), [BM83361](#), [BM83367](#), [BM83443](#), [BM83449](#), [BM83461](#), [BM83467](#), [BM83549](#), [BM83561](#), [BM83567](#)

**Crimp connectors w/o inspection hole, Model(s):** [BM014191](#), [BM014311](#), [BM014371](#), [BM014431](#), [BM014491](#), [BM015251](#), [BM015311](#), [BM015371](#), [BM015431](#), [BM015491](#), [BM016251](#), [BM016311](#), [BM016371](#), [BM016431](#), [BM016491](#), [BM017311](#), [BM017371](#), [BM017431](#), [BM017491](#), [BM018311](#), [BM018371](#), [BM018431](#), [BM018491](#), [BM018551](#), [BM019311](#), [BM019371](#), [BM019431](#), [BM019491](#), [BM019611](#), [BM031371](#), [BM031431](#), [BM031491](#), [BM031551](#), [BM031611](#), [BM032371](#), [BM032431](#), [BM032491](#), [BM032551](#), [BM032611](#), [BM033371](#), [BM033431](#), [BM033491](#), [BM033551](#), [BM033611](#), [BM033671](#), [BM034431](#), [BM034491](#), [BM034551](#), [BM034611](#), [BM034671](#), [BM035491](#), [BM035551](#), [BM035611](#), [BM035671](#), [BM036491](#), [BM036551](#), [BM036611](#), [BM036671](#), [BM036691](#)

**Crimp connectors, double hole tongue, Model(s):** [BM73210](#)

**Crimp connectors, fork, Model(s):** [BM01420](#), [BM01426](#), [BM01523](#), [BM01526](#)

**Crimp connectors, tongue 45 degrees, Model(s):** [BM0141945](#), [BM0143145](#), [BM0143745](#), [BM0144345](#), [BM0144945](#), [BM0152545](#), [BM0153145](#), [BM0153745](#), [BM0154345](#), [BM0154945](#), [BM0162545](#), [BM0163145](#), [BM0163745](#), [BM0164345](#), [BM0164945](#), [BM0173145](#), [BM0173745](#), [BM0174345](#), [BM0174945](#), [BM0183145](#), [BM0183745](#), [BM0184345](#), [BM0184945](#), [BM0185545](#), [BM0193145](#), [BM0193745](#), [BM0194345](#), [BM0194945](#), [BM0195545](#), [BM0196145](#), [BM0313745](#), [BM0314345](#), [BM0314945](#), [BM0315545](#), [BM0316145](#), [BM0323745](#), [BM0324345](#), [BM0324945](#), [BM0325545](#), [BM0326145](#), [BM0333745](#), [BM0334345](#), [BM0334945](#), [BM0335545](#), [BM0336145](#), [BM0336745](#), [BM0344345](#), [BM0344945](#), [BM0345545](#), [BM0346145](#), [BM0346745](#), [BM0354945](#), [BM0355545](#), [BM0356145](#), [BM0356745](#)

**Crimp connectors, tongue 90 degrees, Model(s):** [BM014199](#), [BM014319](#), [BM014379](#), [BM014439](#), [BM014499](#), [BM015259](#), [BM015319](#), [BM015379](#), [BM015439](#), [BM015499](#), [BM016259](#), [BM016319](#), [BM016379](#), [BM016439](#), [BM016499](#), [BM017319](#), [BM017379](#), [BM017439](#), [BM017499](#), [BM018319](#), [BM018379](#), [BM018439](#), [BM018499](#), [BM018559](#), [BM019319](#), [BM019379](#), [BM019439](#), [BM019499](#), [BM019559](#), [BM019619](#), [BM031379](#), [BM031439](#), [BM031499](#), [BM031559](#), [BM031619](#)

[BM032379](#), [BM032439](#), [BM032499](#), [BM032559](#), [BM032619](#), [BM033379](#), [BM033439](#), [BM033499](#), [BM033559](#), [BM033619](#),  
[BM033679](#), [BM034439](#), [BM034499](#), [BM034559](#), [BM034619](#), [BM034679](#), [BM035499](#), [BM035559](#), [BM035619](#), [BM035679](#),  
[BM805379](#), [BM805439](#), [BM806499](#), [BM807499](#), [BM808499](#), [BM809499](#), [BM831499](#), [BM831619](#), [BM832619](#)

**Splicing wire connectors**, Model(s): [BM00160](#), [BM00162](#), [BM00170](#), [BM00260](#), [BM00262](#), [BM00270](#), [BM00360](#),  
[BM00362](#), [BM00370](#), [BM80160](#), [BM80260](#), [BM80360](#)

**Terminal connectors**, Model(s): [BM00101](#), [BM00102](#), [BM00107](#), [BM00108](#), [BM00109](#), [BM00113](#), [BM00114](#), [BM00119](#),  
[BM00120](#), [BM00125](#), [BM00126](#), [BM00131](#), [BM00132](#), [BM00137](#), [BM00143](#), [BM00152](#), [BM00153](#), [BM00201](#), [BM00202](#),  
[BM00207](#), [BM00208](#), [BM00209](#), [BM00219](#), [BM00220](#), [BM00225](#), [BM00226](#), [BM00231](#), [BM00232](#), [BM00237](#), [BM00243](#),  
[BM00252](#), [BM00253](#), [BM00313](#), [BM00314](#), [BM00319](#), [BM00320](#), [BM00325](#), [BM00326](#), [BM00331](#), [BM00332](#), [BM00337](#),  
[BM00338](#), [BM00343](#), [BM00344](#), [BM00352](#), [BM00353](#), [BM01450](#), [BM01525](#), [BM01531](#), [BM01537](#), [BM01543](#), [BM01549](#),  
[BM01550](#), [BM01560](#), [BM01625](#), [BM01631](#), [BM01637](#), [BM01643](#), [BM01649](#), [BM01650](#), [BM01660](#), [BM01731](#), [BM017313](#),  
[BM017314](#), [BM01737](#), [BM017374](#), [BM01743](#), [BM017434](#), [BM01749](#), [BM017494](#), [BM01750](#), [BM01760](#), [BM017604](#), [BM01831](#),  
[BM018313](#), [BM018314](#), [BM01837](#), [BM018373](#), [BM018374](#), [BM01843](#), [BM018433](#), [BM018434](#), [BM01849](#), [BM018494](#), [BM01850](#),  
[BM01855](#), [BM01860](#), [BM018604](#), [BM01931](#), [BM019313](#), [BM019314](#), [BM01937](#), [BM019374](#), [BM01943](#), [BM019433](#), [BM019434](#),  
[BM01949](#), [BM019494](#), [BM01950](#), [BM01955](#), [BM019554](#), [BM01960](#), [BM019604](#), [BM01961](#), [BM019614](#), [BM02050](#), [BM02425](#),  
[BM02431](#), [BM02437](#), [BM02443](#), [BM02449](#), [BM02525](#), [BM02531](#), [BM02537](#), [BM02543](#), [BM02549](#), [BM02625](#), [BM02631](#),  
[BM02637](#), [BM02643](#), [BM02649](#), [BM02661](#), [BM02731](#), [BM02737](#), [BM02743](#), [BM02749](#), [BM02761](#), [BM02831](#), [BM02837](#),  
[BM02843](#), [BM02849](#), [BM02861](#), [BM02931](#), [BM02937](#), [BM02943](#), [BM02949](#), [BM02961](#), [BM03137](#), [BM031373](#), [BM031374](#),  
[BM03143](#), [BM031433](#), [BM031434](#), [BM03149](#), [BM031494](#), [BM03155](#), [BM031554](#), [BM03160](#), [BM031604](#), [BM03161](#), [BM031614](#),  
[BM03237](#), [BM032373](#), [BM032374](#), [BM03243](#), [BM032433](#), [BM032434](#), [BM03249](#), [BM032494](#), [BM03255](#), [BM032554](#),  
[BM03260](#), [BM03261](#), [BM032614](#), [BM03337](#), [BM033373](#), [BM033374](#), [BM03343](#), [BM033433](#), [BM033434](#), [BM03349](#),  
[BM033494](#), [BM03355](#), [BM033554](#), [BM03360](#), [BM03361](#), [BM033614](#), [BM03367](#), [BM033674](#), [BM03443](#), [BM034435](#),  
[BM03449](#), [BM034493](#), [BM034494](#), [BM034495](#), [BM03455](#), [BM034554](#), [BM034555](#), [BM03460](#), [BM034605](#), [BM03461](#),  
[BM034614](#), [BM034615](#), [BM03467](#), [BM034674](#), [BM034675](#), [BM03543](#), [BM035433](#), [BM03549](#), [BM035493](#), [BM03555](#),  
[BM03560](#), [BM03561](#), [BM03567](#), [BM03649](#), [BM03655](#), [BM03660](#), [BM03661](#), [BM03667](#), [BM03669](#), [BM037494](#), [BM037554](#),  
[BM037604](#), [BM037614](#), [BM037674](#), [BM04137](#), [BM04143](#), [BM04149](#), [BM04161](#), [BM04237](#), [BM04243](#), [BM04249](#), [BM04261](#),  
[BM04343](#), [BM04349](#), [BM04361](#), [BM71537](#), [BM71637](#), [BM71643](#), [BM71737](#), [BM717374](#), [BM71743](#), [BM717434](#), [BM71837](#),  
[BM71843](#), [BM718434](#), [BM71849](#), [BM718494](#), [BM71943](#), [BM719434](#), [BM71949](#), [BM719494](#), [BM71955](#), [BM719554](#), [BM71961](#),  
[BM719614](#), [BM72300](#), [BM73143](#), [BM731434](#), [BM73149](#), [BM731494](#), [BM73155](#), [BM731554](#), [BM73161](#), [BM731614](#), [BM73243](#),  
[BM73249](#), [BM73255](#), [BM73261](#), [BM73300](#), [BM73349](#), [BM73355](#), [BM73361](#), [BM73367](#), [BM734495](#), [BM73455](#), [BM734555](#),  
[BM73461](#), [BM734615](#), [BM73467](#), [BM734675](#), [BM73555](#), [BM73561](#), [BM73567](#), [BM73661](#), [BM73667](#), [BM737614](#), [BM90107](#),  
[BM90108](#), [BM90113](#), [BM90114](#), [BM90119](#), [BM90120](#), [BM90125](#), [BM90126](#), [BM90131](#), [BM90132](#), [BM90137](#), [BM90143](#), [BM90150](#),  
[BM90151](#), [BM90207](#), [BM90208](#), [BM90213](#), [BM90219](#), [BM90220](#), [BM90225](#), [BM90226](#), [BM90231](#), [BM90232](#), [BM90237](#),  
[BM90243](#), [BM90250](#), [BM90251](#), [BM90314](#), [BM90319](#), [BM90320](#), [BM90325](#), [BM90326](#), [BM90331](#), [BM90332](#), [BM90337](#),  
[BM90343](#), [BM90350](#)

Last Updated on 2026-02-10

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2026 UL LLC."